## IN THE UNITED STATES FATERITY AND TRADEMARK OFFICE

In re application of:		)	Attorney Docket No. 082669045008
	Corral, Bradley R. et al.	)	
Application	No.: 10/750,799	)	
Filed:	January 2, 2004	)	
For:	PRODUCTION LINE BANDING SYSTEM	)	
Examiner:	Durand, Paul R.	)	
Art Unit:	3721	)	
Confirmation No.: 1828		)	

## AMENDMENTS TO DRAWING

In FIG. 3, shorten the lead line from the numeral 38 and add numeral 166 and a lead line both as shown in the corrected FIG. 3 attached hereto.

In FIG. 5, amend the dimensional lines 66 and 68 as shown in the attached corrected FIG.

In FIG. 8, correctly locate the fence post 81 in the cradles 50, 82 and add a new numeral 81 and lead line and delete the existing numeral 81 and lead line, all as shown in the attached corrected FIG. 8.

In FIG. 12, add the double headed arrow as shown in the attached corrected FIG. 12.

In FIG. 14, add the band 88 and add the numeral 50 and lead line, both as shown in the attached corrected FIG. 14.

In FIG. 15, continue the drawing of the band 88 and add the numeral 50 and lead line, both as shown in the attached corrected FIG. 15.

5.

Response to Office Action Dated June 14, 2004

In FIG. 16, delete the upper numeral "100" and lead line, remove the numeral 81 and lead line and the numeral 50 and lead line, and place an arrowhead on the lead line from the numeral 34, all as shown on the attached amended FIG. 16.

In FIG. 17, add the numeral 88 and lead line as shown in the attached amended FIG. 17.

In FIG. 18, delete the lower numeral 81 and replace with the numeral 149 as shown in the attached corrected FIG. 18.